## PUBLIC WORKS DEPARTMENT

## ADMINISTRATION

3505 Butti Way Carson City, NV 89701-3498 Ph: 775-887-2355 Fx: 775-887-2112

#### FLEET SERVICES

3303 Butti Way, Building 2 Carson City, NV 89701-3498 Ph: 775-887-2356 Fx: 775-887-2258

### OPERATIONS

(Water, Sewer, Wastewater, Streets, Landfill, Environmental) 3505 Butti Way Carson City, NV 89701-3498 Ph: 775-887-2355 Fx: 775-887-2112

## ENGINEERING/ TRANSPORTATION/ CAPITAL PROJECTS 3505 Butti Way

3505 Butti Way Carson City, NV 89701-3498 Ph: 775-887-2355 Fx: 775-887-2112

## BUILDING and SAFTEY PERMIT CENTER

2621 Northgate Lane, Suite 62 Carson City, NV 89706-1319 Ph: 775-887-2310 Fx: 775-887-2202

## PLANNING

2621 Northergate Lane, Suite 62 Carson City, NV 89706-1319 Ph: 775-887-2180 Fx: 775-887-2278

# **CARSON CITY NEVADA**

**Consolidated Municipality and State Capital** 



May 29, 2103

LATE MATERIAL

MEETING DATE 6-6-13

ITEM # 2-2

David Bruketta Carson City Public Works, Utility Manager 3505 Butti Way Carson City NV 89701

Re: Current status of the Brown Street properties

Dear Mr. Bruketta

On May 28, 2013 a walk around inspection was conducted, by Carson City Public Works Environmental Control Supervisor Kelly Hale, and Carson City Public Works Utility Manager David Bruketta, at the properties listed below:

008-303-21, 3679 Gordon Street 008-303-36, 1630 Brown Street 008-303-37, 1636 Brown Street 008-303-39, 1650 Brown Street 008-303-16, 3689 Gordon Street 008-303-15, 3689 Gordon Street

The purpose of this site visit was to determine, as much as practical, if the site conditions have substantially changed since the June 2011 Phase I Environmental Site Assessment was performed.

The site has some areas of disturbed soil (see attached photos) and some debris (trash) has been dumped onto the site. There is no evidence of soil staining, or odors that would indicate any dumping of liquid materials, above what has been previously noted as possible waste vehicle fluids. There were no containers, or drums seen on the site. The areas of disturbed earth all appear to be native soils, and there is no evidence seen of large scale excavations.

There are quite a few places where there are pieces of broken pipe, bricks, concrete, and other "construction" type debris. There are a few areas of the

property which have roofing materials (These appear to be mostly asphalt shingles.) on them, some partially buried.

The location of the historic septic tank has not been determined, and the tank was not located.

The overall site condition does not appear to be substantially different from what was previously noted in the Phase I Assessment documentation. Pictures taken during the walk through inspection are attached

If you have any questions regarding this report, please contact me at 775-283-7376 or Khale@carson.org.

Respectfully,

Kelly Hale, Environmental Control Supervisor

Attachments























